

US Department of Energy Groundwater Database Groundwater Master Report

Installation Name, State: Amchitka
Responsible DOE Office: Office of Legacy Management

Plume Name: No plume identified at Milrow
Remediation Contractor: S.M. Stoller Corporation

Report Last Updated: 2009

Contaminants

Halogenated VOCs/SVOCs Present? **No**
Fuel Present? **No**
Metals Present? **No**
Isotopes Present? **No**
Explosives Present? **No**
Other Contaminants? **No**
Tritium Present? **No**
Nitrates Present? **No**
Sulfates Present? **No**

Hydrogeology

Conduit Flow? Depth (feet): **0**
Multiple Units Affected? Avg Velocity (feet/year): **0**

Plume Information (no source)

Source Area of Plume (acres): **0**
Plume Status **No Response**

Remedial Approach

Remedy Name	Status	Start Date	End Date
monitoring only	Proposed		

Groundwater Use / Exit Strategy

Potable? Does an Exit Strategy Exist? **No**
Sole Source Aquifer? Basis for Exit Strategy: **No Response**

Environmental Indicators (EIs)

Groundwater Migration Under Control? **Need More Info** Current Human Exposure Acceptable? **Need More Info**
Confirmed by Lead Regulator? Confirmed by Lead Regulator?

Regulatory

Decision Document? **No Response** Lead Regulatory Agency: **Other**
Regulatory Position on Groundwater Use Same as Site? Regulatory Driver: **Other**

Comments

No plume has been identified at Milrow. Long-term surveillance and maintenance will continue at the site.