





Center Hill Dam Safety Project Overview


Saddle Dam
Embankment
RCC Berm

Main Embankment & Left Rim
Grouting and Barrier Wall

Legend

-  **COMPLETED: Grouting 2008-2011**
-  **COMPLETED: Barrier Wall 2012-2015**
-  **FUTURE: RCC Berm 2016-2019**
-  **FUTURE: Site Restoration 2016-2019**

Center Hill Dam Safety Remaining Activities



Key Dates:

January 2017 - Decision on Interim Pool Raise (Go or No Go)

July 2018 - RCC Berm Evaluated; Pool Restrictions Removed

